

Master data

Appliances properties: Ofen Innovativ OI GmbH - Profi 40-2

Date of entry May 29, 2019

Manufacturer Ofen Innovativ OI GmbH

Model Profi 40-2

Nominal heat output [kW] 8.6

Declared nominal space heating output [kW]

Continuous burning appliance

Type test standard DIN EN 12815

Year of testing 2017

Test laboratory DBI-Gastechnisches Institut gGmbH Freiberg

Number of test laboratory 1

Number of test report DBI F 16/01/0362

Flue gas values

Woo	d
Flue gas mass flow [g/s]	8
Flue gas mass flow [g/s]	4
Necessary flue draught [Pa]	2

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)

Connectivity to the central heating system

General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

^{*}A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Norm : Cookers Evaluation D - 1.BImSchV Stufe 2 Grandfathering A - Austrian regulation referred to Art. 15a B-VG ✓ CH - Swiss clean air act ✓ F - Crédit d'impôt à la transition énergétique ✓

Evaluation of emission	data and efficiency	Lianite briguettes
Lvaluation of Citiosion	uala and emblemen	LIGITIC DITUUCILES

Evaluation of emission data and efficiency Wood

Norm : Cookers	Evaluation
D - 1.BImSchV	!

Evaluation of emission data and efficiency Pellets

Norm : Cookers	Evaluation
D - 1.BlmSchV	!



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information