

Appliances properties: Oranier Heiztechnik GmbH - Sando 60 II - 7969

waster data	M	laster	data
-------------	---	--------	------

Date of entry Feb 18, 2025 Manufacturer Oranier Heiztechnik GmbH Model Sando 60 II **Product code** 7969 Nominal heat output [kW] 8 Declared nominal space heating output [kW] Partial load [kW] 2.4 Part load space heating output [kW] 2.4 Continuous burning appliance Type test standard DIN EN 16510-2-6 Year of testing Strojirensky Zkusebni Ustav s.p. **Test laboratory Number of test laboratory** Number of test report 30-17197/T

Flue gas value	S
----------------	---

	Pellets
Flue gas mass flow [g/s]	5.9
Flue gas mass flow [g/s]	118
Necessary flue draught [Pa]	13

Further important characteristics of the appliance

Suitability for installation to a shared flue¹⁾

Connectivity to the central heating system

General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

^{*}A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Evaluation of emission data and efficiency Pellets

EU- Roomheater fired by wood pellets accoding to EN 14785	Evaluation
EU - Regulation (EU) 2015/1185 (Ecodesign)	✓
D - 1.BlmSchV	Stufe 2
A - Austrian regulation referred to Art 15a B-VG	✓
CH - Swiss clean air act	✓
DK - Danish regulation for air pollution from wood burners	✓
F - Crédit d'impôt à la transition énergétique	√ 7 ☆
I - Italian Decree No. 186	· 中的中



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information