

Appliances properties: Lohberger GmbH - Varioline LM 50-Z

Master data

Date of entry	Jul 26, 2022
Manufacturer	Lohberger GmbH
Model	Varioline LM 50-Z
Nominal heat output [kW]	8
Declared nominal space heating output [kW]	3.7
Nominal water heating output [kW]	4.3
Water operating pressure [bar]	3
Continuous burning appliance	_
Type test standard	DIN EN 12815
Year of testing	2015
Test laboratory	TGM-Versuchsanstalt Heizung und Lüftung
Number of test laboratory	26
Number of test report	TGM-VA HL 8239

Flue gas values

	Wood
Flue gas mass flow [g/s]	7.2
Flue gas mass flow [g/s]	144
Necessary flue draught [Pa]	12

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)



Connectivity to the central heating system



General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

^{*} A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

EU-Cooker according to EN 12815 EU - Regulation (EU) 2015/1185 (Ecodesign) D - 1.BImSchV A - Austrian regulation referred to Art. 15a B-VG CH - Swiss clean air act F - Crédit d'impôt à la transition énergétique I - Italian Decree No. 186

Evaluation of emission data and efficiency Wood

Norm : Cookers	Evaluation
D - 1.BlmSchV	· !

Evaluation of emission data and efficiency Pellets

Norm : Cookers	Evaluation
D - 1.BlmSchV	



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information