

Appliances properties: skantherm GmbH & Co. KG - mandø

Master data		
Date of entry	Mar 6, 2012	
Manufacturer	skantherm GmbH & Co. KG	
Model	mandø	
Nominal heat output [kW]	6	
Continuous burning appliance	_	
Type test standard	DIN 18891	
Year of testing	1984	
Test laboratory	Prüfstelle der Ruhrkohle-Verkauf GmbH	
Number of test laboratory	27	
Number of test report	91 84 96	
Flue gas values		Wood
Flue gas values Flue gas mass flow [g/s]		Wood 5
Flue gas mass flow [g/s]		5
Flue gas mass flow [g/s] Flue gas mass flow [g/s]		5 368
Flue gas mass flow [g/s] Flue gas mass flow [g/s]		5 368
Flue gas mass flow [g/s] Flue gas mass flow [g/s] Necessary flue draught [Pa]		5 368

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

^{*} A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Norm DIN EN 13240: Roomheater for wood logs EU - Regulation (EU) 2015/1185 (Ecodesign) D - 1.BImSchV According to the transitional rule §26 the appliance can be used until 31.12.2017 CH - Swiss clean air act

DK - Danish regulation for air pollution from wood burners

F - Crédit d'impôt à la transition énergétique

I - Italian Decree No. 186

Evaluation of emission data and efficiency Lignite briquettes

Norm DIN EN 13240 (Intermittent burning): Roomheater with flat-layer firing

D - 1.BImSchV

According to the transitional rule §26 the appliance can be used until 31.12.2017



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information