

Appliances properties: Austroflamm GmbH - Prima STM/KMG

Master data

Date of entry May 12, 2015

Manufacturer Austroflamm GmbH

Model Prima STM/KMG

Nominal heat output [kW]

Declared nominal space heating output [kW]

Continuous burning appliance

Thermal output 21,600

Type test standard DIN EN 13240

Year of testing 2006

Test laboratory RRF Rhein-Ruhr-Feuerstättenprüfstelle GmbH

Number of test laboratory 2

Number of test report RRF - 40 06 1084

Further important characteristics of the appliance

Suitability for installation to a shared flue 1)

Connectivity to the central heating system

General technical approval for room sealed operation

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

6

¹⁾ For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

^{*} A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Norm DIN EN 13240: Roomheater for wood logs EU - Regulation (EU) 2015/1185 (Ecodesign) □ - 1.BImSchV A - Austrian regulation referred to Art 15a B-VG CH - Swiss clean air act □ K - Danish regulation for air pollution from wood burners F - Crédit d'impôt à la transition énergétique

Evaluation of emission data and efficiency Lignite briquettes	
U-Roomheater accroding to EN 13240	Evaluation
EU - Regulation (EU) 2015/1185 (Ecodesign)	_
D - 1.BImSchV	❖
	Grandfathering
- Austrian regulation referred to Art 15a B-VG	_
CH - Swiss clean air act	

I - Italian Decree No. 186



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information