

Number of test laboratory Number of test report

Further important characteristics of the appliance

General technical approval for room sealed operation

Appliances properties: Spartherm Feuerungstechnik GmbH - Speedy M (Bauart A; ab 07.2012)

Date of entry
Feb 18, 2015

Manufacturer
Spartherm Feuerungstechnik GmbH
Model
Speedy M (Bauart A; ab 07.2012)

Nominal heat output [kW]
8

Continuous burning appliance
Type test standard
DIN EN 13229
Year of testing
Test laboratory

RRF Rhein-Ruhr-Feuerstättenprüfstelle GmbH

RRF - 29 11 2819

Flue gas values	
	Wood
Flue gas mass flow [g/s]	5.35
Flue gas mass flow [g/s]	324
Necessary flue draught [Pa]	12

Suitability for installation to a shared flue¹⁾

Connectivity to the central heating system

1) For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

^{*}A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

Evaluation of emission data and efficiency Wood

EU-Inset appliance according to EN13229	Evaluation
EU - Regulation (EU) 2015/1185 (Ecodesign)	*
D - 1.BlmSchV	Stufe 2
A - Austrian regulation referred to Art 15a B-VG	*
CH - Swiss clean air act	*
DK - Danish regulation for air pollution from wood burners	*
F - Crédit d'impôt à la transition énergétique	7☆
I - Italian Decree No. 186	南南南

Evaluation of emission data and efficiency Lignite briquettes

Norm : Inset appliances (with closed firedoor)	Evaluation
D - 1.BlmSchV	1



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information