

## Appliances properties: Gast - Metallwaren GmbH & Co. KG - Oskar 900

Master data		
Date of entry	Jul 18, 2017	
Manufacturer	Gast – Metallwaren GmbH & Co. KG	
Model	Oskar 900	
Nominal heat output [kW]	6	
Continuous burning appliance	_	
Type test standard	DIN EN 12815	
Year of testing	2016	
Test laboratory	Technische Universtität Wien	
Number of test laboratory	7	
Number of test report	PL-15094-P	
Flue gas values		Wood
Flue gas mass flow [g/s]		8
Flue gas mass flow [g/s]		276.2
Necessary flue draught [Pa]		12.1
Further important characteristics of the appliance		
Suitability for installation to a shared flue <sup>1)</sup>		_
Connectivity to the central heating system		_
General technical approval for room sealed operation		_

<sup>1)</sup> For unsealed operation it is possible to install the appliances to a shared flue system (please see installation manual).

On behalf of the manufacturer, the HKI Industrieverband e.V. hereby confirms compliance with the respective requirements\* in accordance with 1.BImSchV. The type test report of the fireplace has been submitted to the HKI Industrieverband e.V.

<sup>\*</sup> A green check mark with a "1" indicates that the requirements of the 1st BImSchV are fulfilled, a green check mark with a "2" indicates that the 2nd level of the 1st BImSchV is fulfilled. A yellow check mark shows that the transitional regulation of the 1st BImSchV is fulfilled and a red line means that the 1st BImSchV is not fulfilled.

## Norm : Cookers D - 1.BImSchV A - Austrian regulation referred to Art. 15a B-VG Evaluation Stufe 2 Grandfathering

CH - Swiss clean air act	<b>*</b>
F - Crédit d'impôt à la transition énergétique	5☆

## Evaluation of emission data and efficiency Lignite briquettes

Evaluation of emission data and efficiency Wood

Norm : Cookers	Evaluation
D - 1.BlmSchV	ļ

## Evaluation of emission data and efficiency Pellets

Norm : Cookers	Evaluation
D - 1.BlmSchV	!



No symbol means that there are no requirements.

No measuring values are available for this fuel, operation with this fuel is not permitted

Here you will find further information